



Fuel oil spraying on hot spots


Fire risk

Fuel oil feeding systems are by nature known potential leaking points
Under pressure, any leak becomes a random oil spray, hence the fire risk

A recent event



Two filters sprayed MDO on the turbocharger air inlet casing just above



Fire in engine room broke out at once leading to important damages

Segregating oil spray from engine room hot spots minimizes the risk level

As far as practicable spray guards could be placed over and around potential leaking sections